INFORMAL SOLICITATION No.<u>5712</u>

MOLD REMEDIATION AT 5043 DELRIDGE AVE SW

ADDENDUM NO.ONE (1) Issue Date <u>11/30/2022</u>

This Addendum containing the following revisions, additions, deletions and/or clarifications, is hereby made a part of this solicitation and Contract Documents for the above-named project. Bidders/Proposers shall take this Addendum into consideration when preparing and submitting their response to this solicitation.

SUPPLEMENTAL INFORMATION

Item 1 Included with this addendum is an Asbestos Report with pictures also available at https://photos.app.goo.gl/Bp4RZYbkemoK3jCP9

END OF ADDENDUM NO. ONE (1)

4601

NVL Laboratories, Inc.
4708 Aurora Ave N, Seattle, WA 98103
Tel: 206.547.0100 Emerg.Pager: 206.344.1878
Fax: 206.634.1936 1.888.NVL.LABS (685.5227)

CHAIN of CUSTODY SAMPLE LOG

BATCHID

	Client	Seattle Housing Auth	nority	NVI F	NVL Batch Number			
	Street	3803 S Willow St. Se	attle, WA 98	2110	Job Number	802094 OD		
					otal Samples	14		
		VINCENT SCOTT SS-056(98126) 056	(98136)	Turn	Around Time 1-1- 2-1- 4-1- F	Hrs 2 Days Ars 3 Days 2 Please call for TAT less th		
	Phone: ((206) 722-2586 F	ax: (206) 72		mail address <u>vscott</u> (206) 465-76	@seattlehousing.or	<u>g</u>	
	Asbestos Air			NIOSH 7402)				
	x Asbestos Bulk			PLM (EPA Point Count)				
	METALS Total Metals TCLP	Det. Limit Mate ☐ ppm (AAS) ☐ Ai ☐ ppb (GFAA) ☐ Di	r ix r Filter rinking water ust/wipe	Paint Chips Paint Chips (Area) Waste Water	RCRA Metals	All 8 Lead (Pb) Mercury (Hg) Selenium (Se)	ther Metals All 3 Copper (Cu) Nickel (Ni) Zinc (Zn)	
	Other Types of Analysis		sance Dust spirable Dust		the district materials.	-		
	Condition of Pack	age: Good Dam	aged (no spil	lage) [] Severe dama	ge (spillage)			
0126	Seq. # Lab ID	Client Sam	ple Number	Comments			A/R	
98126 9402 56-5043A	1	5043 A	VSAB OI	Bedroum 1	Wall		ND	
WOY	2 5043	3, 11 "	11 02	Bathroom	wall		<	
TO A	Delric	19e 11 11	11 03	Bedroom #	2 culing		/_	
0 50431	4 WY.S		" 04	Beardoin #	Caling			
56	6 4 1	lex) 11 C	11 06	Entry Ha	11 wall			
	7	// // D	11 17	and Both	1119			
	8		01	2 4 09111	waa			
	9	4308 1	ISAB 08	Kitchen Ce	ilinc.		ND	
	6810 430	11 11 80	11 09	HONWAN (Vaset Will	/	/	
21065	_11 _SW	(11 2	" 10	Launday Ra	om Cuilir	r		
56 A350	12 Bevery	158 " "	" 11	Bedivom #	2 Culing	7		
	13 Pl.	11 11	" 12	Bathxoom	way			
	14 (4P	lex) // 4	"_13	Living Room	Culing			
	15		11 14		au		1)	
	Sampled b	Print Below Vincent Scott	Sign Relo	was lant	Company	Date	Time	
		y Vincent Scott	1/1/10	and Scale	SHA	10/1/04	9.00ain	
Ì	Received b	10	21 C	and scale		10/19/09	18.069	
	Analyzed b	THE CAN PROPERTY	- P	100	NUL	10/16/19	4125016	
	Results Called by	The state of the s	- 07		10000	10/10/03	11/3/1/1	
	Results Faxed by							
1			-11				la and	
	Composite Analyz		unt samples	all samples will be dis if results are >1%. (5 I Scott with results.		eks atter analysis.		



4708 Aurora Ave. N., Seattle, WA 98103 Tel: 206.547.0100. Fax: 206.634.1936 www.nvllabs.com

For the scope of accreditation under NVLAP Lab Code 102063-0

Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Seattle Housing Authority

Address: 3803 S Willow St.

Seattle, WA 98118

Batch #: 2912271.00

Client Project #: 802094 OD

Date Received: 10/14/2009

Samples Received: 14

Samples Analyzed: 14

Method: EPA/600R-93/116

None Detected

Asbestos Type: %

Asbestos Type: %

None Detected

ND

None Detected

Attention: Mr. Vincent Scott

Project Location: SS-056 (98126) 056 (98136)

Lab ID: 29090837 Client Sample #: 5043 A VSAB 01

Location: SS-056 (98126) 056 (98136)

Description: Off-white compacted powdery material with paint Layer 1 of 3

Non-Fibrous Materials:

Other Fibrous Materials:% Asbestos Type: % Calcareous particles, Binder/Filler, Paint

None Detected

Layer 2 of 3 Description: Off-white compacted powdery material with paper

> Non-Fibrous Materials: Other Fibrous Materials:% Asbestos Type: %

Calcareous particles, Binder/Filler Cellulose 55% None Detected

Layer 3 of 3 Description: Off-white chalky material with paper

> Other Fibrous Materials:% Non-Fibrous Materials:

Fine particles, Gypsum/Binder Cellulose 23%

> Glass fibers 2%

ND

Lab ID: 29090838 Client Sample #: 5043 A VSAB 02

Location: SS-056 (98126) 056 (98136)

Description: Off-white compacted powdery material with paint Layer 1 of 3

Non-Fibrous Materials:

Other Fibrous Materials:%

Fine particles, Binder/Filler, Paint None Detected None Detected ND

Layer 2 of 3 Description: Off-white compacted powdery material with paper

> Non-Fibrous Materials: Other Fibrous Materials:% Asbestos Type: %

> > Fine particles, Binder/Filler Cellulose 47%

None Detected ND

Layer 3 of 3 Description: Off-white chalky material with paper

> Non-Fibrous Materials: Other Fibrous Materials:% Asbestos Type: %

Fine particles, Gypsum/Binder Cellulose 18%

Lab ID: 29090839 Client Sample #: 5043 A VSAB 03

Location: SS-056 (98126) 056 (98136)

Sampled by: Client

Analyzed by: Nadezhda Prysyazhnyuk Date: 10/15/2009

Reviewed by: Nick Ly

Date: 10/15/2009 Technical Director



4708 Aurora Ave. N., Seattle, WA 98103 Fax: 206.634.1936 Tel: 206.547.0100. www.nvllabs.com

For the scope of accreditation under NVLAP Lab Code 102063-0

Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Seattle Housing Authority

Address: 3803 S Willow St.

Seattle, WA 98118

Batch #: 2912271.00

Client Project #: 802094 OD

Date Received: 10/14/2009

Samples Received: 14

Samples Analyzed: 14

Method: EPA/600R-93/116

Attention: Mr. Vincent Scott

Layer 2 of 3

Project Location: SS-056 (98126) 056 (98136)

Description: Off-white compacted powdery material with paint Layer 1 of 3

Non-Fibrous Materials:

Other Fibrous Materials:%

None Detected

Asbestos Type: %

None Detected

Calcareous particles, Binder/Filler, Paint

Description: Off-white compacted powdery material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 35%

None Detected ND

Layer 3 of 3 Description: Off-white chalky material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 20%

None Detected

Glass fibers 2%

Lab ID: 29090840 Client Sample #: 5043 B VSAB 04

Location: \$\$-056 (98126) 056 (98136)

Layer 1 of 3

Description: Layered off-white compacted powdery material with paint

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected ND None Detected ND

Description: Off-white compacted powdery material with paper Layer 2 of 3

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 32%

None Detected

Layer 3 of 3 Description: Off-white chalky material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 18%

None Detected

Glass fibers 2%

Lab ID: 29090841 Client Sample #: 5043 C VSAB 05

Location: SS-056 (98126) 056 (98136)

Layer 1 of 3

Description: Off-white compacted powdery material with paint

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected

None Detected ND

Sampled by: Client

Analyzed by: Nadezhda Prysyazhnyuk

Date: 10/15/2009

Reviewed by: Nick Ly

Date: 10/15/2009

Nick Ly, Technical Director



4708 Aurora Ave. N., Seattle, WA 98103 Tel: 206.547.0100. Fax: 206.634,1936 www.nvllabs.com

For the scope of accreditation under NVLAP Lab Code 102063-0

Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Seattle Housing Authority

Address: 3803 S Willow St.

Seattle, WA 98118

Batch #: 2912271.00

Client Project #: 802094 OD

Date Received: 10/14/2009

Samples Received: 14

Samples Analyzed: 14

Method: EPA/600R-93/116

Attention: Mr. Vincent Scott

Project Location: SS-056 (98126) 056 (98136)

Layer 2 of 3 Description: Off-white compacted powdery material with paper

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 30%

None Detected

Layer 3 of 3 Description: Off-white chalky material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 22%

None Detected

Glass fibers 3%

Lab ID: 29090842 Client Sample #: 5043 C VSAB 06

Location: SS-056 (98126) 056 (98136)

Layer 1 of 3 Description: Layered off-white compacted powdery material with paint

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected

None Detected ND

Layer 2 of 3 Description: Off-white compacted powdery material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 34%

None Detected

Description: Off-white chalky material with paper Layer 3 of 3

Non-Fibrous Materials:

Other Fibrous Materials:%

Glass fibers

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 27%

2%

None Detected ND

Lab ID: 29090843 Client Sample #: 5043 D VSAB 07

Location: SS-056 (98126) 056 (98136)

Layer 1 of 3

Description: Off-white compacted powdery material with paint

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected

None Detected

Layer 2 of 3 Description: Off-white compacted powdery material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 33%

None Detected

Sampled by: Client


Analyzed by: Nadezhda Prysyazhnyuk

Reviewed by: Nick Ly

Date: 10/15/2009

Date: 10/15/2009

Nick Ly, Technical Director



4708 Aurora Ave. N., Seattle, WA 98103 Tel: 206.547,0100. Fax: 206.634.1936 For the scope of accreditation under NVLAP Lab Code 102063-0

www.nvllabs.com

Bulk Asbestos Fibers Analysis

By Polarized Light Microscopy

Client: Seattle Housing Authority

Address: 3803 S Willow St.

Seattle, WA 98118

Batch #: 2912271.00

Client Project #: 802094 OD

Date Received: 10/14/2009

Samples Received: 14

Samples Analyzed: 14

Method: EPA/600R-93/116

Attention: Mr. Vincent Scott

Project Location: SS-056 (98126) 056 (98136)

Layer 3 of 3 Description: Off-white chalky material with paper

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

ND

Fine particles, Gypsum/Binder

Cellulose 18%

None Detected

Lab ID: 29090844 Client Sample #: 4308 1 VSAB 08

Location: SS-056 (98126) 056 (98136)

Layer 2 of 3

Layer 1 of 3 Description: Off-white compacted powdery material with paint

Non-Piprous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected ND None Detected ND

Description: Off-white compacted powdery material with paper

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellulose 28%

None Detected ND

Layer 3 of 3 Description: Off-white chalky material with paper

Non-Fibrous Materials:

Other Fibrous Materials:%

Glass fibers

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 16%

3%

None Detected ND

Lab ID: 29090845 Client Sample #: 4308 1 VSAB 09

Location: SS-056 (98126) 056 (98136)

Layer 1 of 3 Description: Off-white compacted powdery material with paint

Non-Fibrous Materials:

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler, Paint

None Detected ND None Detected ND

Layer 2 of 3 Description: Off-white compacted powdery material with paper

Non-Fibrous Materials

Other Fibrous Materials:%

Asbestos Type: %

Calcareous particles, Binder/Filler

Cellylose 40%

None Detected ND

Description: Off-white chalky material with paper Layer 3 of 3

Non-Fibrous Materials:

Other Fibrous Materials: %

Asbestos Type: %

Fine particles, Gypsum/Binder

Cellulose 18%

None Detected ND

Glass fibers 3%

Sampled by: Client

Analyzed by: Nadezhda Prysyazhnyuk

Reviewed by: Nick Ly

Date: 10/15/2009

Date: 10/15/2009

Nick Ly, Technical Director